

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Tuesday, February 5, 2013

Kalamazoo River / Enbridge Spill

Water / Sediment Temperatures

| Location | Water Temp. (°F) | Sediment Temp. (°F) |
|------------------|------------------|---------------------|
| C0.4 Water Gauge | N/A* | N/A* |
| C3.2 Water Gauge | N/A* | N/A* |
| E0.5 Water Gauge | N/A* | N/A* |
| E2 Water Gauge | N/A* | N/A* |
| E4 Water Gauge | N/A* | N/A* |

*Water/Sediment Temperatures were unable to be collected due to ice formation along the river bank.

Prepared by:
Karen Berecz
START-USEPA
Situation Unit



1. Talmadge Creek flowing to confluence observed icing conditions.



2. Confluence observed icing conditions.



3. C0.4 Boat Launch observed river icing conditions.



4. C0.4 Boat Launch observed river icing conditions.



5. Ceresco Dam impoundment observed river icing conditions.



6. Ceresco Dam impoundment observed river icing conditions.



7. Ceresco Dam impoundment observed icing conditions.



8. MP7.25 downstream from Angler's Bend observed river icing conditions.



9. MP9.75 upstream from Wattles Road Bridge observed river icing conditions.



10. C3.2 Pole Barn observed core logging procedures.



11. C3.2 Boat Launch observed river icing conditions.



12. MP14.25 LDB observed RI team.



13. MP15.25 South Mill Pond observed river icing conditions.



14. MP15.25 South Mill Pond observed back water icing conditions.



15. MP15.50 North Mill Pond observed river icing conditions.



16. MP15.65 North Mill Pond culverts observed icing conditions.



17. MP21.50 observed river icing conditions.



18. MP21.50 Oxbow observed icing conditions.



19. MP27.00 Shady Bend Campground observed river icing conditions.



20. E2 Boat Launch observed river icing conditions.



21. MP36.50 downstream from 35th Bridge observed icing conditions.



22. Morrow Lake Delta observed icing conditions.



23. Morrow Lake Delta observed icing conditions.



24. Morrow Lake Delta observed icing conditions.



25. Morrow Lake Neck/Morrow Lake Delta observed icing conditions.



26. Morrow Lake observed icing conditions.